



Case Study: American Wood Fibers Circleville, OH Facility Plant Safety Review: One Year Later

Exponent:

**Mark Fecke, P.E., CFEI
Justin Bishop, Ph.D., CFEI**

**American Wood Fibers:
Stephen Faehner**

July 29, 2013



Exponent®




Who Are The Authors



- Justin Bishop – Electrical Engineer, Fire and Explosion Investigation, Hazard Analysis



- Mark Fecke – Mechanical Engineer, Fire and Explosion Investigation, Hazard Analysis




- Stephen Faehner – VP of Industrial and BioEnergy Sales




Outline

- Who is Exponent
- OSHA General Duty Clause
- Plant Overview
- Scope of 2012 Inspection (3-4 hr looking at general plant safety, dust issues, electrical issues)
- One Year Later
- Good Practices & Needs Improvement
- Conclusions



Engineering Sciences

- Biomedical Engineering
- Electrical Engineering & Computer Science
- Engineering Management Consulting
- Mechanical Engineering
- Materials & Corrosion Engineering
- Polymer Science & Materials Chemistry
- Thermal Sciences



Environmental Sciences

- Ecological & Biological Sciences
- Environmental & Earth Sciences



Health Sciences

- Chemical Regulation & Food Safety
- Epidemiology, Biostatistics & Computational Biology
- Exposure Assessment & Dose Reconstruction
- Occupational Medicine & Environmental Health
- Toxicology & Mechanistic Biology




Civil & Construction

- Buildings & Structures
- Civil Engineering
- Construction Consulting
- Industrial Structures



Technology Development



Transportation

- Biomechanics
- Human Factors
- Statistical & Data Sciences
- Vehicle Engineering
- Visual Communications



Exponent Offices



Hangzhou



Derby and Harrogate



Düsseldorf



Basel



OSHA General Duty Clause

- **OSHA General Duty Clause (Section 5(a)(1)):**
 - Each employer [...] shall furnish to each of his employees employment and a place of employment which are free from recognized hazards that are causing or are likely to cause death or serious physical harm to his employees
- **General duty clause citations**
 - Reference consensus standards such as NFPA standards and guidelines
- **The hazard caused or was likely to cause death or serious physical harm**
- **Feasible means to correct the hazard were available**



Identifying Hazards

■ Structured Analysis

- Process Hazard Analysis (PHA)
 - Checklist Evaluations
 - What-If Studies
 - Hazard and Operability (HazOp) Studies
 - Fault Tree Analysis
 - Failure Modes Effects Analysis
- Gap Analysis
- Quantitative Risk Assessment

■ Site Inspection

- Typically one day on site
- Review of site safety and hazards
- Based on non-conformance with
 - Industry Guidelines
 - Codes
 - Standards
 - OSHA Regulations
 - Good Engineering Practice

Exponent performs all of the above



AWF - Circleville, OH

- Receives raw material used to create pellets is delivered via trucks
- Several SBU's handling 125,000 tons annually
- 20 Tractor Trailers in / out of the plant per day
- Pellet Fuel & Wood Flour production





Scope: 2012 Plant Inspection

- 3 hours on-site
- High-level review focused on:
 - Best Practices
 - Hazard Identification
 - Safety
 - Fugitive Dust
 - Electrical Systems
 - Sensors and Control
- Standards and Recommended Practices
 - NFPA 664, 70, 499, 505 • OSHA NEP • 29 CFR 1910....





Documentation: 2012

Good Practices

- Incident reporting
- Safety review
- Process flow diagram (PFD)
- Employee training schedule
- Accident and safety correction reports
- Housekeeping

Needs Improvement

- Raw Material Housekeeping
- Process Hazard Analysis
- Classified (Hazardous) Locations
- Preventative Maintenance
- Sensor/interlock testing/review
- P&ID

Employee Training Matrix

Legend:

- Required within past 12 mths
- Completed past 12 mths
- Observatory
- Training is not required
- For only BSH Cases (NO COLORS)



Documentation: 1 Year Later

Good Practices

- Preventative Maintenance*
 - New PM system (eRPortal)*
 - System tracks work orders and generates PM work orders*
- Sensor/interlock testing/review*
 - Starting to test interlocks and sensor operations*
 - Verifying LOTO program*

Needs Improvement

- Preventative Maintenance
- Sensor/interlock testing/review

eRPortal

Home | Assets | Work Orders | PMS | Systems Config | Help

Work Order Finder | Work Order Entry | Asset Finder | Logout

My Maintenance Dashboard

Open WOs	Unassigned WOs	Overdue WOs	Open PMS	Assets Down	Completed Today
484	343	405	161	9	13

Open Work Orders for Division 58

WO#	Asset Code	Asset Description	Work Requested	Assigned To	Requested By
208352	58Misc	Miscellaneous Repairs	1) Find out and label what each riser feeds 2) Find		Justin Heier
208351	58AL1	AIRLOCK	1) Coupler leaky by AL-1		Justin Heier
208349	58Misc	Miscellaneous Repairs	Lights burnt out above AC-100 & AD-100		Justin Heier
208348	58VU15	UNLOADER	VU-15 Leaking around rubber boot		Justin Heier
208347	58SC13	SCREWCONVEYOR	1) Under Silo 13, dust is leaking everywhere around		Justin Heier
208346	58AL14	AIRLOCK	1) Packings need to be replaced on airlock - leaking		Justin Heier
208345	58TN02	TANK	1) Tank is leaking from the Top 2) After leak is		Justin Heier
208344	58TN01	TANK	1) Tank is leaking from the Top 2) Cleanup entire		Justin Heier
208342	58AL15	AIRLOCK	1) Packings on airlock are leaking 2) Check chain		Justin Heier

Unassigned Work Order By Division

WO #	Asset Code	Description	History	Work Requested	Created	WO Type	Requested By	Department
208352	58Misc	Miscellaneous Repairs	History	1) Find out and label what each riser feeds 2) Find out what each	7/25/13	Safety	Justin Heier	58MFG
208351	58AL1	AIRLOCK	History	1) Coupler leaky by AL-1	7/25/13	Repair	Justin Heier	58MFG
208349	58Misc	Miscellaneous Repairs	History	Lights burnt out above AC-100 & AD-100	7/25/13	Repair	Justin Heier	58MFG
208348	58VU15	UNLOADER	History	VU-15 Leaking around rubber boot	7/25/13	Repair	Justin Heier	58MFG
208347	58SC13	SCREWCONVEYOR	History	1) Under Silo 13, dust is leaking everywhere around drive end to	7/25/13	Repair	Justin Heier	58MFG

*Based on conversations with plant representative



Prevention of Fugitive Dust: 2012

Good Practices

- Dust collector outside
 - Deflagration vents
 - Isolation
- Repair leaks instead of increasing housekeeping





Prevention of Fugitive Dust: 2012

Needs Improvement

- Dust collector inside the plant
- Identifying leaks and areas of potential leaks is an on going process
- “Duct tape” repairs





Prevention of Fugitive Dust: 1 Year Later

Needs Improvement

- Dust collector inside the plant
- Identifying leaks and areas of potential leaks is an on going process
- "Duct tape" repairs



Good Practices

- No more "Duct tape" repairs*
- When leaks are found, the process is shut down and the leak is repair with a long term fix*

*Based on conversations with plant representative



Housekeeping: 2012

- **Good Practice**
 - Brooms and shovels to clean fugitive dust
 - Clean spills/leaks when they are found
- **Be Careful**
 - Compressed air to blow down surfaces
 - Can create airborne combustible dust
 - Tests to determine allowable pressures
 - Not at the Circleville, OH plant
- **Needs Improvement**
 - Still some trouble areas
 - Raw material area
- **Key Comment**
 - Vacuums may be APPROVED for a combustible dust...
 - BUT may not be approved/certified for use in a classified area






Housekeeping: 1 Year Later


- Needs Improvement

- Still some trouble areas
- Raw material area



- Working towards a solution*

- Need economical solution*
- Evaluating vibratory shakers and oscillating fans to knock down dust from ledges/rafters*





Process Hazard Analysis (PHA): 2012

- **Required by Section 4.3 of the 2012 version of NFPA 664**
 - “A process analysis is a methodical review of the facility, each operation housed within, and the identification of where a hazard exists.”
- **Good Practices**
 - Safety review Checklist generated based on best practices 5 years ago
 - Each AWF facility was inspected for compliance with this Checklist
 - Identified major areas for improvement
- **Needs Improvement**
 - Checklist based on best practices is not necessarily a “methodical review of the facility”
 - Checklist should be reviewed and updated to include current standards and guidelines
 - Audits should be performed on a routine basis





Emergency Action Plans and Fire Fighting: 2012

- Required by NFPA 664 Section 10.12 Emergency Planning and Response
 - “A written emergency plan shall be developed for preventing, preparing for, and responding to work-related emergencies including but not limited to fire and explosion.”
- **Good Practices**
 - Specific written procedure for pellet mill fires.
 - Typical ignition sources identified
 - Combustible dust hazards explained
 - Emergency actions listed
 - Training enhanced by use of case studies
 - Specific written procedure for silo fires.
 - Same as above
 - Use inert gas to smother fire; do not use water
 - Experienced fire suppression contractor utilized
- **Needs Improvement**
 - Communication with local fire departments in pre-planning exercise
 - Training with local fire departments in pre-planning exercise
 - Increased awareness of silo fire hazards within the fire protection community.



Bonding and Grounding: 2012

- **Good Practices**
 - Grounding structures and equipment
 - Bonding equipment and piping
- **Needs Improvement**
 - Scheduled inspections and maintenance
 - Scheduled testing of grounding/bonding system





Bonding and Grounding: 1 Year Later

■ Good Practices

- Grounding structures and equipment
- Bonding equipment and piping
- Scheduled inspections and maintenance*
 - Outside contractor used to evaluate complete grounding/bonding system*
 - Based on their assessment, new procedures will be implemented*
- Scheduled testing of grounding/bonding system*
 - Outside contractor used to evaluate complete grounding/bonding system*
 - Based on their assessment, new procedures will be implemented*

■ Needs Improvement

- Scheduled inspections and maintenance
- Scheduled testing of grounding/bonding system



Electrical Classified (Hazardous) Locations: 2012

- **Good Practices**
 - Most locations have been electrically classified
 - Equipment in classified locations is certified for the area
- **Needs Improvement**
 - Re-evaluation of locations
 - Locations that should be classified are not
 - Some equipment is not certified for use in the classified area





Industrial Trucks: 2012

- Used to move raw material into and out of raw material storage
- **Wood Flour → Group G Dust**
- Type DX (diesel) or EX (electric) industrial trucks required (NFPA 505)
- AWF modifies their mobile equipment to reduce the likelihood of an incident
 - Non Flammable Hydraulic Fluid
 - Automated Fire Suppression
 - Jet Coating Hot Surfaces






Sensor Loop Testing and PLC Functional Checks: 2012

■ Good Practice

- Check sensor loops when installed

■ Needs Improvement



- Regular sensor wiring checks
- Regular PLC functional checks
 - Verify if sensor/wiring fails, it fails safe and alerts operator
- Jumping out sensors
- Temporary sensor wiring is not a long term solution





General and Equipment Wiring: 2012


- Issues observed





Labels and Operator Warnings: 2012

- **Good Practices**
 - Identifying labels on switches
 - Some labeling on PLC/sensor wiring
- **Needs Improvement**
 - Identifying labels on switches and PLC/sensor wiring
 - Descriptive warnings for the operator





Elimination and Detection of Ignition Sources: 2012

Good Practices

- CCTV
- Spark detection
- Rock Trap
- Magnetic separators
- Raw Material Room Lighting
- Abort gate
- Rotary valves
- CO₂ extinguishing bottles on Pellet Mills
- Dust Collection

Needs Improvement

- Any unclassified sources inside classified area prohibited
- Dust Collectors placed outside
- Temperature Sensors on bearing





Conclusion

- A 3-hour high level plant review was conducted in 2012.
- The AWF plant review identified procedures that were good practices and others that need improvement.
 - Best Practices
 - Hazard Identification
 - Safety
 - Fugitive Dust
 - Electrical Systems
 - Sensors and Control
- Over the last year the plant focused on improving bonding/grounding, eliminating duct tape repairs, and scheduling preventative maintenance.
- AWF is trying to facilitate a safe work environment by identifying and mediating potential safety issues and bad practices.



Thank You

- Jennifer Hedrick, Executive Direct of Pellet Fuels Institute
- Stephen Faehner, VP - Industrial and Bio Energy Sales
- Edward Owens, P.E., VP - Operations Support
- Brian Mischnick, GM of AWF-Circleville
- Jason Brengman – AWF-Circleville Plant Engineer



Case Study: American Wood Fibers Circleville, OH Facility Plant Safety Review: One Year Later

Justin Bishop


jbishop@exponent.com

4580 Weaver Parkway, Suite 100

Warrenville, IL 60555

630-658-7522

July 29, 2013



Exponent®